


N/A

## CDCV857DGG

Part Number:	CDCV857DGG
Producer / Brand:	N/A
Product description:	IC SSTL-II PLL CLK-DRVR 48TSSOP
Datasheets:	
RoHS Status:	 Azad / RoHS Rêberê Rêber
Ship Ji:	Hong Kong
Rêwirinê:	DHL/Fedex/TNT/UPS/EMS

**SERDANA DAXWAZA BIDEŞTIXISTINÊ**

Wêne dibe ku temsîl bikin. Ji bo agahdariya hilberên taybetmendiyê binirxînin.













### Specifications of CDCV857DGG

PART NUMBER	CDCV857DGG
ÇÊKER	N/A
TERÎF	IC SSTL-II PLL CLK-DRVR 48TSSOP
RÊVEBIRIYA AZAD FREE / ROHS STATUS	Azad / RoHS Rêberê Rêber
KARTA DANÛSTENDINÊ	
VOLTAGE - PARGÎDANIYÊ	2.3 V ~ 2.7 V
AWA	PLL Clock Driver
SUPPLIERS PACKAGE PACKAGE	48-TSSOP
DORANÎ	-
RÊJEYA - BARKIRINA DERVEYÎ: DERVE	1:10
PACKAGING	Tube
SAZ / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
KARÛABR	Clock
NAMES	296-24143-5 CDCV857DGG-ND
OPERASYONA GERM	0°C ~ 85°C
HEJMARA CIRCUITS	1
TÎPA ÇIYAYÊ	Surface Mount
NERMKIRINA NAVNETEWÊYÎ YA NAVNETEWÎ (MSL)	2 (1 Year)
RÊVEBIRIYA AZAD FREE / ROHS STATUS	Lead free / RoHS Compliant
BEYAN	Clock
FREQUENCY - MAX	200MHz
DIVIDER / MULTIPLIER	No/No
VEBIJÊRÎN - INPUT: OUTPUT	Yes/Yes
HEJMARA PARTIYA	CDCV857

### Related Tags

CDCV857DGG	Belavkarê CDCV857DGG	Dabîinkerê CDCV857DGG
Bihayê CDCV857DGG	Wêneyên CDCV857DGG	Wêneyê CDCV857DGG
CDCV857DGG PDF Datasheet	CDCV857DGG Datasheet dakêşin	CDCV857DGG Datasheet
CDCV857DGG Stock	CDCV857DGG bikirin	CDCV857DGG bikirin
CDCV857DGG	Dabîinkerê	Belavkarê

### Berhemên peywendîdar

 <p><b>CDCV857DGGRG4</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48TSSOP          Ez bêzarim: 5405 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCVF111FNG4</b>          Producer: N/A          Terîf: IC CLK BUFFER 1:9 650MHZ 28PLCC          Ez bêzarim: 5389 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV857DGGG4</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48TSSOP          Ez bêzarim: 4677 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV857BGQLR</b>          Producer: N/A          Terîf: IC CLK PLL CLOCK DRVR 56-BGA          Ez bêzarim: 4617 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV857BIDGGR</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48TSSOP          Ez bêzarim: 16291 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV857BDGGRG4</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48TSSOP          Ez bêzarim: 22822 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCVF111FNR</b>          Producer: N/A          Terîf: IC CLK BUFFER 1:9 650MHZ 28PLCC          Ez bêzarim: 7790 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV857BIDGGRG4</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48TSSOP          Ez bêzarim: 19369 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV857DGGR</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48-TSSOP          Ez bêzarim: 5363 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCV857BIDGGG4</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48-TSSOP          Ez bêzarim: 8726 pcs</p> <p><b>RFQ</b></p>
 <p><b>CDCV857BIDGG</b>          Producer: N/A          Terîf: IC SSTL-II PLL CLK-DRVR 48-TSSOP          Ez bêzarim: 10910 pcs</p> <p><b>RFQ</b></p>	 <p><b>CDCVF111FN</b>          Producer: N/A          Terîf: IC CLK BUFFER 1:9 650MHZ 28PLCC          Ez bêzarim: 6603 pcs</p> <p><b>RFQ</b></p>