

N/A

LMK00304SQX/NOPB

Part Number:	LMK00304SQX/NOPB
Producer / Brand:	N/A
Product description	IC CLK BUFFER 3:5 3.1GHZ 32WQFN
Datasheets:	
RoHS Status	Azad / RoHS Rêberê Rêber
Ship Ji	Hong Kong
Rêwirinê	DHL/Fedex/TNT/UPS/EMS

SERDANA DAXWAZA BIDEŞTIXISTINÊ

Wêne dibe ku temsîl bikin. Ji bo agahdariya hilberên taybetmendiyê binirxînin.

Specifications of LMK00304SQX/NOPB

PART NUMBER	LMK00304SQX/NOPB
ÇÊKER	N/A
TERÎF	IC CLK BUFFER 3:5 3.1GHZ 32WQFN
RÊVEBIRIYA AZAD FREE / ROHS STATUS	Azad / RoHS Rêberê Rêber
KARTA DANÛSTENDINÊ	
VOLTAGE - PARGÎDANIYÊ	3.15 V ~ 3.45 V
AWA	Fanout Buffer (Distribution), Multiplexer, Translator
SUPPLIERS PACKAGE PACKAGE	32-WQFN (5x5)
DORANÎ	-
RÊJEYA - BARKIRINA DERVEYÎ: DERVE	3:5
PACKAGING	Tape & Reel (TR)
SAZ / CASE	32-WFQFN Exposed Pad
KARÛABR	HCSSL, LVCMOS, LVDS, LVPECL
OPERASYONA GERM	-40°C ~ 85°C
HEJMARA CIRCUITS	1
TÎPA ÇIYAYÊ	Surface Mount
NERMKIRINA NAVNETEWÊYÎ YA NAVNETEWÎ (MSL)	3 (168 Hours)
RÊVEBIRIYA AZAD FREE / ROHS STATUS	Lead free / RoHS Compliant
BEYAN	CML, HCSSL, HSTL, LVDS, LVPECL, SSTL, Crystal
FREQUENCY - MAX	3.1GHz
VEBIJÊRÎN - INPUT: OUTPUT	Yes/Yes
DETAILED DESCRIPTION	Clock Fanout Buffer (Distribution), Multiplexer, Translator IC 3:5 3.1GHz 32-WFQFN Exposed Pad
HEJMARA PARTIYA	LMK00304

Related Tags

LMK00304SQX/NOPB	Belavkarê LMK00304SQX/NOPB	Dabîinkerê LMK00304SQX/NOPB
Bihayê LMK00304SQX/NOPB	Wêneyên LMK00304SQX/NOPB	Wêneyê LMK00304SQX/NOPB
LMK00304SQX/NOPB PDF Datasheet	LMK00304SQX/NOPB Datasheet dakêşin	LMK00304SQX/NOPB Datasheet
LMK00304SQX/NOPB Stock	LMK00304SQX/NOPB bikirin	LMK00304SQX/NOPB bikirin
LMK00304SQX/NOPB	Dabîinkerê	Belavkarê

Berhemên peywendîdar

<p>LMK00306SQ/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Ez bêzarim: 15141 pcs</p> <p>RFQ</p>	<p>LMK00301SQ/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Ez bêzarim: 16276 pcs</p> <p>RFQ</p>
<p>LMK00306SQE/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Ez bêzarim: 15164 pcs</p> <p>RFQ</p>	<p>LMK00308SQ/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:9 3.1GHZ 40WQFN Ez bêzarim: 16225 pcs</p> <p>RFQ</p>
<p>LMK00308EVM/NOPB Producer: N/A Terîf: BOARD EVAL FOR LMK00308 Ez bêzarim: 337 pcs</p> <p>RFQ</p>	<p>LMK00304SQ/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:5 3.1GHZ 32WQFN Ez bêzarim: 24218 pcs</p> <p>RFQ</p>
<p>LMK00304SQE/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:5 3.1GHZ 32WQFN Ez bêzarim: 16840 pcs</p> <p>RFQ</p>	<p>LMK00306EVM/NOPB Producer: N/A Terîf: BOARD EVAL FOR LMK00306 Ez bêzarim: 409 pcs</p> <p>RFQ</p>
<p>LMK00301SQX/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Ez bêzarim: 17670 pcs</p> <p>RFQ</p>	<p>LMK00304EVM/NOPB Producer: N/A Terîf: BOARD EVAL FOR LMK00304 Ez bêzarim: 425 pcs</p> <p>RFQ</p>
<p>LMK00301SQE/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:10 3.1GHZ 48WQFN Ez bêzarim: 10236 pcs</p> <p>RFQ</p>	<p>LMK00306SQX/NOPB Producer: N/A Terîf: IC CLK BUFFER 3:7 3.1GHZ 36WQFN Ez bêzarim: 19578 pcs</p> <p>RFQ</p>